

#### THE HORSEFLY COMMUNITY CLUB

5772 Horsefly Road P.O. Box 179 Horsefly, BC, VOL 1L0 horseflycc@gmail.com

Aug 1, 2025

# Re: Request for Funding Support – Horsefly Community Hall Roof Replacement and Insulation Project

Dear Mr. Campbell,

The Horsefly Community Club respectfully requests funding support from the Community Works Fund for our roof and insulation upgrade project at the Horsefly Community Hall. This project is a critical first step in a broader energy efficiency initiative that will reduce operating costs, enhance emergency preparedness, and extend the life of our well-used community facility.

## **Project Background and Urgency**

Built in 1955, the Horsefly Community Hall is the cultural and emergency response hub for our rural community of approximately 700 year-round residents. Over the years, the hall has undergone several additions, but the original roof — constructed with rough-sawn 2x8s and insulated with planer shavings and six inches of fiberglass — has never been replaced. A roof inspection conducted in December 2024 revealed approximately 12 holes in the main roof large enough to allow visible daylight and numerous compromised seams. In addition, the roof lacks any underlay, leaving the insulation vulnerable to moisture and degradation.

The ceiling has been identified as a major source of heat loss. However, adding insulation alone would provide limited benefit unless paired with replacement of the roof. Therefore, replacing the roof is the most urgent component of the overall energy efficiency plan. Without it, any insulation upgrades risk being ineffective or quickly damaged.

#### **Project Scope and Cost**

The total estimated cost for replacing the roof and installing additional insulation is \$52,698.80 plus applicable taxes. We have selected a competitive quote from Weatherby's Roofing and

Sheet Metal, a local company based in 150 Mile House, offering superior materials (Pro-Loc panels) and installation features, including:

- Complete removal of existing metal roofing and substrate inspection
- Ice and water membrane installation (lower 6 feet) and synthetic felt underlay
- 26-gauge Pro-Loc metal panels with hidden fasteners and all required flashings
- Cobra venting at ridge and new plumbing boots
- Snow guards for lower roof protection and safety

In addition, the project includes:

- Purchase and delivery of 135 bales of Sopra-Cellulose insulation
- Rental of a blower for installation
- Volunteer installation labour by Horsefly Community Club members

# **Benefits of the Project**

This upgrade will:

- Improve the ceiling insulation value from R-18.86 to R-40
- Cut annual heat loss by over 50%
- Prevent future water and air infiltration
- Reduce heating costs and energy use
- Extend the life and safety of the building
- Enable the hall to continue serving as an emergency response centre

#### **Looking Ahead**

This project is part of a larger vision to modernize the hall with further energy upgrades, including heat pumps, solar panels, new doors and windows, and improved wall insulation. While these additional elements will be pursued as funds become available, the roof replacement is foundational and must come first.

## **Funding and Contributions**

The Horsefly Community Club has secured approximately \$7,000 in reserve funds and expects to raise another \$20,000–\$25,000 in the next year. We are actively pursuing additional funding,

including an application to the Northern Development Initiative Trust and exploring energy rebates and interest-free financing.

We deeply appreciate the CRD's continued support and respectfully request your contribution toward this most critical and time-sensitive component: the roof replacement. Please feel free to contact us with any questions or for further details about this project or our community programming.

Sincerely,

Tanya Tervit
President, Horsefly Community Club
<a href="mailto:horseflycc.president@gmail.com">horseflycc.president@gmail.com</a>

# Summary:

The Community Hall was very sturdily built, mostly using rough-sawn 2x8s. It is insulated with planer shavings, with six inch fiberglass overhead. The floor system appears to be uninsulated, as expected.

I've calculated the R-values of the Main Floor components: walls, ceiling and floor. They are - walls- R-20.01 ceiling- R-18.86 floor- R-4.70

I have calculated the total heat load on the furnace system at six ambient (outdoor) temperatures, +10, 0, -10, -20, -30 and -40C. In all cases the target indoor temperature is 21C.

To sum up the following three pages of calculations,

- 1) Replacing the existing double-glazed R-2.1 windows with standard triple-glazed, low-e, argon filled windows (R-5.5) will reduce the total heat load by only 1.9% at an outdoor temperature of -20C. Total heating load would be reduced from approximately 93,000 Btu/hr to 92,000 Btu/hr, a savings that would amount to just five cents per hour. This would not be cost-effective.
- 2) Adding six inches of blow-in cellulose insulation across the entire attic, which will settle 12% to five and a half inches, will add another R-20. This will reduce the heat loss through the ceiling by half. However, this only amounts to a 6% savings overall, not negligible but certainly not spectacular. It is a very affordable upgrade; a 25lb bale retails for about \$16 and would cover about thirty-six square feet.
- 3) Overcoming air infiltration and exfiltration is, by far, the single greatest challenge for the heating system. This amounts to 56-63% of total heating load.

The main focus of any remedial work should be the air-sealing of the building. The back-stage areas and the so-called 'chair room' behind the wheelchair bathroom were never finished back in 1955. They are planked with ordinary, very drafty shiplap. As a result, the cold air can easily be felt sweeping across the main floor on a cold day, whether the furnace is running or not. Both areas should be clad in foamboard, carefully detailed and drywalled. The shiplap could be first removed before any upgrading work is done, although the labour involved may not be worthwhile.

5) A properly weatherstripped exterior door should be installed leading up the stairs to the sound booth. The sound booth door should be carefully weatherstripped.


The exterior doors are quality doors but were installed by well-meaning amateurs. They need a lot of attention as they are a significant source of air infiltration.

The recessed ceiling lights are not airtight and can be boxed in with homemade foamboard enclosures. I've done this myself in the past with great success.

The furnaces should be provided with outside combustion air, which can fairly easily be pulled from under the front porch. At present they depressurize the building and make the cold drafts worse.

I have a new thermal imaging camera on order. If you need more careful analysis of the building's thermal envelope and calculations of heating system requirements, feel free to call me anytime.

Paul Hearsey




(1)

	Building heat long calentations						2025/2/6
	Q=(A/K) AT where Q = rate of heat transfer trapped the assembly (Blu/hr)  A = area of assembly - may regime e.g. (Blu/hr)  R = K-value, of enline assembly (°F • F2 · hr/Fstu)  AT = temperature difference perween interior and exterior (°F)  - standard interior temperature is 70°F (21°C)						
	Heat losses through ma outdoor ambient-	· h . 11	4//2000	lated to	K-value of		(740+) -40°C
**************************************	Btu/f2	1.0	19	25	3.7	46	55
- R-20.01 R-18.36 R-4.70	and the state of t	5.63k 5.17k 12.60k 19.10k	6.35k 6.02k 12.60k 24.75k	9.34k \$.67k 12.60k 30.81k	12.54k 11.72k 12.60k 36.66k	15,54k 14,57k 12,60k 42,51k	1834k 1742k 12.60k 42.3668kg/hr
	Interview heat lesses, main. Floor-  0; = 0.016 NVAT where constant is the heat capacity of air (Bin/F <sup>3</sup> /°)?  N= estimated air granges for large on pyolished 45HRAS data)=1.6  V= volume of heater space (F <sup>3</sup> )  AT = temperature disprences herren where and exprior (°F)						
•	ontagos ambient		0°C		720°C		
	V=46,000f3	243lk	2536	42.54	56.216	67.86%	85.56kBm/n
	total region as % of THL	45.41k - 56%	558)k 54%	7555k 56%	90.57k	11237k	131.72kBtu/hr 15%


Proposed vindow update 20/25/2/6. Main Floor-6 on main, and 4 bening style 22×54 = 8.25 8 on Heat loss through I unit at, say, 200- (A/K) AT = (8,25/21) ×74 = 291 Bty/hr 291 Bly hr × 6 windows = 1,744 Bly hr total heating load of 200 is calculated to be 93 k Bluffer :. Window JOSES 2 1.9% of total Suppose existing windows (R-21) are upgraved to trave-dozed, sing-stop, love-e, arguestiled, units now windows R-5.5 hour loss 6 x (8.25/5.3) × 74 = 666 Btu/hr heat loss savings 1,744-666 = 1,078 Bty In 6\$4,83/100k = 5.24/m. : 1-20°C, total beating load is reduced from 93k Bluther to 92k Bluther A \$2 first oil is typically tolog of 36,500 blow lifer.

- 4,85% sumages efficiency view is 31,025 blow lifer

- 4,544,\$1.50/lifer, 100,000 bloc cost \$4.83 Existing Observ (hasement) Furnace valed at 117k Stuffer (dated 1997) Lennox (main Floor) Turnace 113k Btuffer



HORSEFLY COMMUNITY HALL heating load calculated for 21°C interior and 20°G exterior.



HORSEFLY COMMUNITY HALL heating load calculated for 21°C interior and -40°C exterior.

2025/2/15