

Corrective Enforcement – Inspection Summary

Permit No.: S9699

Expired: February 19, 2004

Date	Inspection	Status (pass/fail)	Notes
	FOOTING FORMS		
	FOUNDATION FORMS		
	ROUGH-IN FOR RADON		
	PRE-BACKFILL		
	FRAMING		
	UNDER SLAB PLUMBING		
	ROUGH-IN PLUMBING		
	WOOD APPLIANCE CHIMNEY		
	INSULATION VAPOUR BARRIER		
Nov 14, 2002	COMPLETION FINAL	Fail	Deck to be self-supported, not hung off trailer, Handrails and guards required at entry stairs, skirting to allow for ground movement, wood within 8" of ground to be treated, water line to be fitted with a heat tape & insulation, building location survey required or expose survey pins at lot corners & add 1 meter buffer to minimum setbacks
	EXPIRED		