

**INSPECTION ACTIVITY REPORT**  
**Cariboo Regional District**  
**Building Inspection Department**

For the Month of: APRIL 2018

<b>BUILDING INSPECTIONS</b>	<b>INSPECTION STAGE</b>	<b>NUMBER OF INSPECTIONS</b>			
		<b>Central</b>	<b>South</b>	<b>North</b>	<b>TOTAL</b>
	Footing	0	15	3	<b>18</b>
	Foundation	0	9	2	<b>11</b>
	Pre-Backfill	0	7	0	<b>7</b>
	Framing	2	2	2	<b>6</b>
	R.I. for Radon	0	5	0	<b>5</b>
	Plumbing	1	7	1	<b>9</b>
	Insulation	0	8	2	<b>10</b>
	Chimney/FP/WS	0	2	0	<b>2</b>
	Final Inspection	5	12	6	<b>23</b>
	Misc./Other	0	1	0	<b>1</b>
	<b>TOTAL INSPECTIONS</b>	<b>8</b>	<b>68</b>	<b>16</b>	<b>92</b>

File Closed	4	7	2	<b>13</b>
-------------	---	---	---	-----------